		1	1		1	1	1	Cite				
"Damage								Site Inspection	% Work			
#"	Category	Name	Damage Description	Status	Address	Broject #	Project Title	Required?		Approx. Cost	Labor Type	
#	Category		The 4000 ft sq FUMC parsonage community facility	Jialus	Audress	FIOJECL#		Requireus	complete	Approx. Cost		
			was damaged beyond repair and needed to be									
		Duilding 7 Development	demolished ASAP for safety considerations. The cost								Farra Array at and	
262191	٨	- Demolition	for the demolition to the FUMC was \$5000 plus forced labor oversight.	Activo	Port St Joe, Florida			No	100%	\$6,000.00	Force Account and	
262191	A	- Demolition		Active	1001 Constitution			No	100%	\$6,000.00	Contract	
		CDM Danata d	Any donated resources and/or volunteer labor (and									
		EPM Donated	volunteer work related) work need to be under this		Drive , Port St Joe ,				500/			
255131	В	Resources	CAT B	Active	Florida, 32456			No	50%	\$20,000.00	Donated Resources	
			Due to Hurricane Michael affecting all ground and									
			second floor exterior and interior parks,									
			playgrounds, parking lots, signage, storm water,									
			management, structures, utilities, contents, and									
			equipment - entire campus. Volunteer removed									
			sand & debris from both parking lots. Work									
			performed by FA labor, contract, and volunteers.									
			Receipts & documentation forthcoming. Oct 8-9 - In									
			preparation for Hurricane Michael church volunteers									
			sandbagged around all doors and moved things to									
			higher ground. Put elevator in upright and locked									
		EPM Campus Wide	position. Put plastic up about 4 ft. around all		1001 Constitution		EPM Campus Wide					
		October 7-9 &	buildings. Additional emergency repairs have been		Drive, Port St Joe,		Oct 7-9 and Nov				Force Account and	
248729	В	November 25, 2018 -	completed.	Active	Florida, 32456	80035	25th and beyond	Yes	75%	\$50,000.00	Contract	
			purchased tools, Kubota tractor. FA labor and									
			volunteer labor. Floor ventilation systems dried.									
			Squiggles were utilized to assist in removing flood									
			waters. Area was cleared of debris and electrical									
			panels were underwater. Trees and upside down									
			vehicles removed to gain access. Applicant was									
			without power for 16 days. 5 Generators were									
			utilized for lights, air, 2 sump pumps, fans, chain									
			saws and other power tools, refrigeration. Volunteer									
			Labor security was utilized due to not being able to									
			secure the building due to breakage of windows and									
			loss of all exterior and most interior doors. Flooded									
			sheet rook cut out 8â€ [™] to prevent mold, flooring									
			removed due to surge force water flooding, floors									
			and walls sprayed with purchased Shock Wave									
			treatment to prevent mold and mildew for safety of									
			all entering the buildings. Two to three inches of									
			sewage backup took three or four weeks to make									
			sanitary. Some interior, destabilized walls removed.									
			Boarded windows, boarded up many doorways.									
			Tarped the roof over sanctuary and offices. Debris									
			pulled from interior of buildings and placed roadside									
			for County pickup. Plumber hired to fix grinder pump									
			and electrical. Electrical panels made usable until				EPM State Identified					
		EPM 45 days	they can be replaced. Generators utilized for shower		1001 Constitution		45 days (October 10					
		(October 10 to	and laundry trailers brought in for health and safety		Drive, Port St Joe,		to November 24,				Force Account and	
248730	В	November 24, 2018)	of general public utilizing due to no power or water	Active	Florida, 32456	79440	2018)	No	100%	\$115,000.00	Contract	

,,							1			,		
			The Care Closet (originally on 4th street - building									
			owned by the church) - has been serving as a critical									
			facility since the storm providing services city wide.									
			Shortly after the storm the Care Closet moved to a									
			city owned facility so that the pre-school and day									
			care could move in and begin to offer services again									
			due to damage at the church. The care closet									
			continued to provide critical services - clothing, food,									
			and water (essential given half the city was with out)									
			with primarily volunteers at the city facility through									
			February. The care closet beginning March 1st									
			relocated again to a downtown rented 4th street									
			location continuing to provide critical services to									
			Port St Joe and the church as it was required to									
			move out of the city owned facility. The care closet									
			cannot move back into its' pre storm location									
			because of the damage to the church and the need									
			for the church owned building to service the pre-									
			school and day care. Rent for the new emergency									
			care closet location is @\$2,200 /mo. until repairs									
		EPM Temporary	are completed at church (may need to apply for time		1001 Constitution							
		Facility for Care	extension) Temporary Contract to be uploaded for		Drive , Port St. Joe,		EPM Temporary					
255144	в	Closet Critical Service		Active	Florida, 32456	80045	Rented Facility	Yes	50%	\$39,600.00	Contract	
233144			chiefbener reinburgenene.	Active		00043	incluced rectincy		30/0	\$55,000.00	contract	
			Storm Water Drainage - 2 Major 4 ft diameter city /									
			community / church storm water drains run directly									
			through church property with some extent under									
			buildings. Both drains have possible damage due to									
			high head water intrusion and release of 15+ ft of									
			water above grade during the event. One drain runs									
			under the MLC and around the property near the									
			bayside playground and storm water retention pond.									
			The second runs underneath the sanctuary building.									
		Storm Water	Both need scoping and engineering analysis by				Utilities and Storm				Force Account and	
253105	С	Drainage	engineering firm. Repairs may be needed.	Active	Port St Joe, Florida	80081	Water Drainage	Yes	0%	\$55,000.00	Contract	
233103		Di unidge	Parking Lots, Lot Areas, and Surrounding Structures,	Active		00001		103	070	\$55,000.00	Contract	
			Lot Signage, and General Church Signage - Areas									
			include 2 Parking lots (new lot @ 15,000 ft sq - old									
			lot behind church @ 6000 ft sq), lot areas, and									
			surrounding structures - Parking lots, lot walk-ways,									
			sidewalks, entry and exit channels, require replaced									
			and/or repaired for structural integrity, washout,									
		Darking Lats Lat	and safety. Signage includes: 1) Church sign 10' x									
		Parking Lots, Lot	6' illuminated electric sign â€" destroyed 2) Post									
		Areas, and	(wooden) church sign – destroyed 4' x 6' 3)									
		Surrounding	Historic signage for church â€" 1960's sign		1001 Constitutio		Deubline Lete					
		Structures, Lot	constructed of RR ties – damaged 4) All other		1001 Constitution		Parking lots,					
240724	c	Signage, and General	signage lost or damaged - replacement & repair	A	Drive, Port St Joe,	70.422	signage, walkways,	N	250/	¢115 000 00	Force Account and	
248731	С	Church Signage	necessary	Active	Florida, 32456	79432	sidewalks	Yes	25%	\$115,000.00	Contract	

			1		1		1				1	
			Water retention pond - drainage pipes in parking lot -									
			sump pump in elevator shaft. 1) 5- 12†inlet									
			CMP -8†inlet x 1000â€ [™] replaced in parking lot									
			area due to damages 2) 3 â€" to the pond 2 â€" to									
			the city drainage systems 3) Pond is contaminated									
			due to debris from the surge force waters from the									
			bay, local damaged structures, and flying debris.									
			6' to 8' water inundation above grade from									
			the surge. The Pond needs to be drained, cleaned of									
			debris and waste, dried, rebuilt as is needed. 4)									
			Sump pump in elevator flooded shaft â€" completed									
		 drainage pipes in 	by Contract 5) May need larger pond for storm									
		parking lot - sump	water runoff due to loss of natural (numerous very		1001 Constitution							
		pump in elevator	large pine trees) surface and groundwater		Drive, Port St Joe,		Water Rentention					
248732	D	shaft	adsorption and evaporation processes.	Active	Florida, 32456	79431	Pond	Yes	10%	\$235,000.00	Contract	
			sf: Offices/Music Room/Classrooms 2nd floor; 3,200									
			sf Includes all internal and external: concrete, wood,									
			steel, dry wall and particle boards; roofing; brick									
			structures; Offices, Classrooms, Closets, built-in book									
			cases, Hallways, Doors and Stairways to the west of									
			the attached Bldg#3-Great Hall. All exterior walls and									
			roof, all first and second floor windows (29) broken									
			or breached allowing moisture intrusion. 14 large									
			stained glass pieces. 1st; 2nd fl. and balcony floors;									
			walls; doors (36 including 4 exterior and 4 historic);									
			electrical; plumbing; roofing; ceiling; attached									
			seating (pews); walls and windows; door failures.									
			Roof replaced in kind shingles. Shingled roof									
			damaged, leaks in offices, classrooms, stairwells,									
			storage and equipment room, bathrooms, choir									
			room, doors warped or gone, locking system on									
			glass doors damaged beyond repair; glass inlay with									
			metal casings. 2nd floor balcony stripped. Fire									
			suppression system was damaged. All insulation									
			violated. Bldg. #1 - The Sanctuary Bell Tower (Aprx.									
			Size = 1000 ft sq) all Lexan covered windows out;									
			railings gone – copper roof damaged. Bldg railings									
			gone. The organ - part equipment (i.e will fall out									
			of building and actually ended up outside on the				2 bldgs-Sanctuary -					
		Building 1 - Sanctuary	road) and part attached structure was destroyed -		1001 Constitution		Bell tower (Historic):					
		and Offices -	the pipes and chambers were damaged beyond		Drive, Port St Joe,		equipment for both					
248733	E	Structure	repair and are attached facility components. The	Active	Florida, 32456	79433	and contents	Yes	5%	\$1,000,000.00	Contract	
			Bldg. #3 - Great Hall – (Aprx. size ~ 14,000 ft sq)									
			Damage occurred due to Hurricane Michael; portion									
			of campus that includes the new lobby area, the new									
			grand kitchen, the new fellowship / services area,									
			and the outdoor rotunda: internal and external									
			doors and internal and external walls, all windows,									
			all floors and bathroom tile, all plumbing and sinks,									
			all ceilings, kitchen, pumps and sumps, elevator, AV,									
			HVAC system, roof, closets, hallways, electrical and									
			plumbing. Elevator - The elevator reconstruction /									
			repair has been completed replacement and/ or									
			repair. Lobby elevator shaft damaged. Fire		1001 Constitution							
		-	suppression system was damaged along with all		Drive, Port St Joe,		Buildings 2, 3, 4, 5,					
248735	E	- Structure	insulation being moisture damaged.	Active	Florida, 32456	80021	6&7	Yes	0%	\$225,000.00	Contract	
										, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

 Rotunda - (Aprx. Size ~ 3,500 ft sq) - The ade, railings, lighting, fans, electrical, AV, y floor damages, pillars, entry way doors, alkways, concrete slab damaged due to e Michael created heavy damages and Railings rebuild complete on Rotunda; elaid and need to be relaid again - 									
y floor damages, pillars, entry way doors, alkways, concrete slab damaged due to e Michael created heavy damages and Railings rebuild complete on Rotunda;									
alkways, concrete slab damaged due to e Michael created heavy damages and Railings rebuild complete on Rotunda;									
e Michael created heavy damages and Railings rebuild complete on Rotunda;									
Railings rebuild complete on Rotunda;									
Railings rebuild complete on Rotunda;									
-				1					
icy repair needs to be redone for									
on. The fire suppression system was		1001 Constitution							
				Buildings 2 3 4 5					
	Activo	1 ' '	80031		Vac	0%	¢125 000 00	Contract	
	Active	FIUTIUA, 52450	80021	0 & /	res	0%	\$125,000.00	Contract	
Contents - See Attached List. Note that									
mponents are listed here as contents and as									
ral loss. The organ consul is mobile (and									
p on the street with the piano - both				2 bldgs-Sanctuary -					
and is listed in this contents list. The organ		1001 Constitution		Bell tower (Historic):					
d chambers are defined in the structural		Drive, Port St Joe,		equipment for both					
	Active	Florida, 32456	79433	and contents	Yes	0%	\$200,000.00	Contract	
-Due to Hurricane Michael: Contents within									
ling damaged from A) the walls, doors, and									
failure B) due to roof and window									
from wind resulting in possible additional		1001 Constitution							
				Buildings 2, 3, 4, 5,					
	Active	1 ' '	80021		Yes	0%	\$65,000,00	Contract	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					0,0	\$05,000,00	Contract	
**Remove duplicate damage - 1 line item									
	Active				Ves	0%	\$95,000,00	Contract	
	Active				105	0/0	\$55,000.00	contract	
*********	Activo				Voc	0%	\$25,000,00	Contract	
	Active	FIULIUA, 52450		+	165	0/0	\$23,000.00	Contract	
1 2007 Toursta mini una damana d									
, , , ,									
vided) destroyed due to hurricane. 5. Pull									
moker trailer 1 destroyed due to hurricane -									
ire. 6. Pull behind smoker trailer 2		1001 Constitution							
d due to hurricane - See Picture. 7. Ford		Drive, Port St Joe,							
		Florida, 32456	81063	1st UMC Vehicles	Yes	0%	\$150,000.00	Contract	
nger Bus All documentation forthcoming	Active	FI0110a, 52450							
	Active	FIOTIDA, 32430							
nger Bus All documentation forthcoming	Active	FI0100, 32430							
nger Bus All documentation forthcoming – Church Storage Pole Barn - Equipment -	Active								
nger Bus All documentation forthcoming â€" Church Storage Pole Barn - Equipment - ment under the pole barn was damaged	Active	10102, 52430							
nger Bus All documentation forthcoming â€" Church Storage Pole Barn - Equipment - ment under the pole barn was damaged emoved via flood waters and has been listed	Active	10102, 52430		Buildings 2, 3, 4, 5,					
	I along with some insulation being moisture lon south wall. Due to Hurricane Michael: Contents within ing damaged from A) the walls and failure due to flood surge of 7 - 16 ft plus wave action, B) due to roof failure resulting onal top down water damage, C) door Contents - See Attached List. Note that mponents are listed here as contents and as ral loss. The organ consul is mobile (and o on the street with the piano - both and is listed in this contents list. The organ d chambers are defined in the structural Due to Hurricane Michael: Contents within ing damaged from A) the walls, doors, and failure B) due to roof and window from wind resulting in possible additional nwater damage, C) door failures, and D) See Attached List **Remove duplicate damage - 1 line item age structure ******* 1. 2007 Toyota mini van damaged due to hurricane. 2. 2018 Ford mini bus bus) damaged (totaled) due to hurricane. 3. yle UMCOR Cargo trailer 1 (w/contents - list wided) destroyed due to hurricane. 4. U E UMCOR Cargo trailer 2 (w/contents - list wided) destroyed due to hurricane. 5. Pull moker trailer 1 destroyed due to hurricane -	I along with some insulation being moisture Active I on south wall. Active Due to Hurricane Michael: Contents within ing damaged from A) the walls and failure due to flood surge of 7 - 16 ft plus wave action, B) due to roof failure resulting onal top down water damage, C) door Contents - See Attached List. Note that mponents are listed here as contents and as ral loss. The organ consul is mobile (and oo on the street with the piano - both and is listed in this contents list. The organ d chambers are defined in the structural Active Due to Hurricane Michael: Contents within ing damaged from A) the walls, doors, and failure B) due to roof and window from wind resulting in possible additional nwater damage, C) door failures, and D) Active See Attached List Active ***Remove duplicate damage - 1 line item age structure ******** Active 1. 2007 Toyota mini van damaged due to hurricane. 3. yle UMCOR Cargo trailer 1 (w/contents - list wided) destroyed due to hurricane. 4. U e UMCOR Cargo trailer 1 (w/contents - list wided) destroyed due to hurricane. 5. Pull moker trailer 1 destroyed due to hurricane -	a long with some insulation being moisture lon south wall. Drive, Port St Joe, Florida, 32456 Due to Hurricane Michael: Contents within ing damaged from A) the walls and failure due to flood surge of 7 - 16 ft plus wave action, B) due to roof failure resulting onal top down water damage, C) door Contents - See Attached List. Note that mponents are listed here as contents and as ral loss. The organ consul is mobile (and o on the street with the piano - both and is listed in this contents list. The organ d chambers are defined in the structural d chambers are defined in the structural d failure B) due to roof and window from wind resulting in possible additional nwater damage, C) door failures, and D) See Attached List 1001 Constitution Drive, Port St Joe, Florida, 32456 ***Remove duplicate damage - 1 line item ges structure ************************************	a long with some insulation being moisture lon south wall. Drive, Port St Joe, Florida, 32456 80021 Due to Hurricane Michael: Contents within ing damaged from A) the walls and failure due to flood surge of 7 - 16 ft plus wave action, B) due to roof failure resulting onal top down water damage, C) door Contents - See Attached List. Note that mponents are listed here as contents and as ral loss. The organ consul is mobile (and o on the street with the piano - both and is listed in this contents list. The organ d chambers are defined in the structural Active 1001 Constitution Drive, Port St Joe, Florida, 32456 Due to Hurricane Michael: Contents within ing damaged from A) the walls, doors, and failure B) due to roof and window from wind resulting in possible additional nwater damage, C) door failures, and D) 1001 Constitution Drive, Port St Joe, Florida, 32456 **Remove duplicate damage - 1 line item ges structure ******** Active Florida, 32456 ******** remove - duplicate damage - 1 1 only 1 line item per building ************************************	Lalong with some insulation being moisture Lon south wall. Due to Hurricane Michael: Contents within ing damaged from A) the walls and failure due to flood surge of 7 - 16 ft plus wave action, B) due to roof failure resulting mol top down water damage, C) door Contents - See Attached List. Note that mponents are listed here as contents and as ral loss. The organ consul is mobile (and on the street with the piano - both and is listed in this contents list. The organ d chambers are defined in the structural Drive, Port St Joe, Florida, 32456 2 bldgs-Sanctuary - Bell tower (Historic): equipment for both and contents Active Florida, 32456 79433 and contents Buildings 2, 3, 4, 5, 6 & 7 2 bldgs-Sanctuary - Bell tower (Historic): equipment for both and contents Drive, Port St Joe, Florida, 32456 80021 2 bldgs-Sanctuary - Bell tower (Historic): equipment for both and contents Buildings 2, 3, 4, 5, 6 & 7 9433 and contents Buildings 2, 3, 4, 5, 6 & 7 9433 Buildings 2, 3, 4, 5, 6 & 7 1001 Constitution Drive, Port St Joe, Florida, 32456 1. 2007 Toyota mini van damaged due to hurricane. 2. 2018 Ford mini bus bus) damaged (totaled) due to hurricane . 1. 2007 Toyota mini van damaged due to hurricane. 2. 2018 Ford mini bus bus) damaged (totaled) due to hurricane . 1. 2007 Cargo trailer 1 (w/contents - list wided) destroyed due to hurricane . 2. DHI Moker trailer 1 destroyed due to hurricane - Drive, Port St Joe, Florida, 32456 1. 2007 Coyota mini van damaged due to hurricane . 3. Vieture Florida, 32456 1. 2007 Coyota mini van damaged due to hurricane . 3. Vieture florida is 32456 3. Vieture florida, 32456 3. Vieture f	Lalong with some insulation being moisture Lon south wall. Drive, Port St Joe, Florida, 32456 80021 6 & 7 Yes Buildings 2, 3, 4, 5, Yes Porte Attrive Florida, 32456 80021 6 & 7 Yes Porte St Joe, 6 & 7 Yes Porte St Joe, Florida, 32456 80021 6 & 7 Yes Porte St Joe, Seo Attached List. Note that mponents are listed here as contents and as ran loss. The organ consul is mobile (and o on the street with the piano - both and is listed in this contents list. The organ of chambers are defined in the structural failure B) due to roof and window from wind resulting in possible additional near the walls, doors, and failure B) due to roof and window from wind resulting in possible additional near the result of a failures, and D) See Attached List *Remove duplicate damage - 1 - only 1 line item publiding 1.2007 Toyota mini van damaged due to hurricane. 2. 2018 Ford mini bus sus) damaged (totaled) due to hurricane. 4. 1.2007 Toyota mini van damaged due to hurricane. 2. 2018 Ford mini bus sus) damaged (totaled) due to hurricane. 4. 2.2017 Coyota mini van damaged due to hurricane. 4. 2.2017 Coyota mini van damaged due to hurricane. 4. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 4. 2.2017 Coyota mini van damaged fue to hurricane. 5. Pull Method betroyed due to hurricane. 4. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 4. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 5. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 4. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 4. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 5. 2.2018 Ford mini bus sus) damaged (totaled) due to hurricane. 5. 2.2018 Ford mini bus 2.2018 For	la long with some insulation being moisture Lon south wall. Drive, Port St Joe, Florida, 32456 Buildings 2, 3, 4, 5, Ves 0% Buildings 2, 3, 4, 5, Ves 0% 6 & 7 Ves 0% 0% 0% 0% 0% 0% 0% 0% 0% 0%	la long with some insulation being moisture Lon south wall. Drive, Port St Joe, Due to Hurricane Michael: Contents within ing damaged from A) the walls and failure due to food surge of 7. 16 ft plus wave action, B) due to roof failure resulting onal top down water damage, C) door Contents - See Attached List. Note that monomes are listed here as contents and as ral loss. The organ and loss contents list. The organ dambers are defined in the structural Contents - See Attached List. Note that monomes are listed here as contents and as ral loss. The organ dambers are defined in the structural Contents - See Attached List. Note that monomes are listed here as contents and as ral loss. The organ dambers are defined in the structural Contents - See Attached List. Note that monomes are listed here as contents and as ral loss. The organ dambers are defined in the structural Content - Stee attached List. Note that monomes list of the structural Content - Stee attached List. Note that monomes are listed here as contents within ing damaged from A) the walls, doors, and failure B) due torof and window from wind resulting in possible additional water damage, C) door failures, and D) Free, Port St Joe, See Attached List ************************************	Jang with some insulation being moisture Lon south wall. Drive, Port SLOe, Florida, 32456 Buildings 2, 3, 4, 5, 80021 Ves 0% \$125,000.00 Contract Lon south wall. Date of Hurricane Michael: Contents within ing damaged from A) the walls and failure due to flood surge of 7-16 fb µus wave action, 8) due to roof failure resulting non lot odow meter damage, c) door Contents - See Attached List. Note that mponents are listed here as contents and as a list led in this content list. The organ on the street with the piano - both and is listed in this contents. The organ 1001 Constitution Drive, Port SLOe, Florida, 32456 Just Part Port SLOE, Part Part SLOE, Part Part SLOE, Part Part SLOE, Part Part Part Part Part Part Part Part

	Bldg. #7 – Community Parsonage – Structure								
	blug. #7 ac Community raisonage ac Structure								
	(Approx. Size ~ 3,923 ft. sq. – including ~ 500 ft.								
	sq.garage.The structure was completely destroyed								
	and has been torn down due to safety issues.								
	Totaled destruction due to A) the walls and windows	5							
	failure due to flood surge of 16 ft. plus resulting								
	wave action, B) due to roof failure resulting in								
	additional top down water damage, C) door and								
Building 7									
Communi									
Parsonage					Buildings 2, 3, 4, 5,				
255141 E Structure	and wash away into debris piles.	Active	Port St Joe, Florida	80021	6 & 7	Yes	0%	\$1,250,000.00	Contract
Building 7				00021				\$1,250,000100	
Communi									
Parsonage					Buildings 2, 3, 4, 5,				
255142 E Equipmen		Active	Port St Joe, Florida	80021	6 & 7	Yes	0%	\$65,000.00	Contract
200142 E Equipmen	Bldg. #7 - Community Parsonage â€" Contents - All	Active	ron stroe, nonua	80021	0 & /	163	070	\$03,000.00	contract
Building									
Communi	5 5				Buildings 2, 3, 4, 5,				
	- Contents Complete contents List TBD.	Active	Port St Joe, Florida	80021	6 & 7	Yes	0%	\$100,000.00	Contract
235145 E Parsonage	- Contents Complete contents List TBD.	Active	Port St Joe, Fiorida	80021	0 & /	res	0%	\$100,000.00	Contract
Duilding 1	- Sanctuary								
	Belltower - ******* Delete - Duplicate Damage - 1 Building 1								
252135 E Equipmen		Active	Port St Joe, Florida			Yes	0%	\$95,000.00	Contract
232135 E Equipinen	The Great Hall damage occurred due to Hurricane	Active	Port St Joe, Fiorida			res	0%	\$95,000.00	Contract
	Michael. Equipment includes multipurpose								
	commercial copier (brand and model #, receipts								
	needed), commercial coffee machine and bar,								
Duilding (computer, lobby elevator door - controls - pump,								
	- Great Hall and AV and Audio located in the fellowship hall.	A	Dant Children Elanista	00001	Buildings 2, 3, 4, 5,		50/	¢02.000.00	Contract
252141 E - Equipme		Active	Port St Joe, Florida	80021	6 & 7	Yes	5%	\$93,000.00	Contract
	Bldg. #1 - Due to Hurricane Michael - Equipment								
	Includes: 1) Upright grand piano is gone. (\$100,000)								
	2) Audio visual equipment (new purchase 2017-18 @								
	\$100,000) 3) Organ (gone) and Pipes (200) damaged	1							
	(\$500,000) – SHIPPO to be advised as ½ of the								
	original historic organ pipes brought over from								
	1800's era missing, organ wooden/metal gone								
	(wood was replaced 20 years ago). 4) All 52 ground								
	level and balcony pews damaged replace / restore								
	(\$300,000). 5) All original equipment chancel				2 bldgs-Sanctuary -				
	furnishings damaged: alar, baptismal find, pulpit,				Bell tower (Historic):				
	- Sanctuary lectern, item stand, two presiders chairs, and two				equipment for both				
252136 E & Offices	Equipment acolyte chairs (\$50,000).	Active	Port St Joe, Florida	79433	and contents	Yes	0%	\$1,050,000.00	Contract
	Bldg. #5 - The FUMC (2500 ft sq) Care Closet, now								
	the temporary location of the day care and								
	preschool was impacted by Hurricane Michael and								
	suffered various and obvious roof and outside wall								
	damages. The metal roof screws need to be re-								
	tightened as a result of wind load stress, various								
	fascia and rake trim damaged, and various roof								
	panels need to be replaced as they failed due to								
	wind load. The inside of the building - electrical,								
	S ,								
	plumbing, insulation, walls, ceilings, floors and								
	plumbing, insulation, walls, ceilings, floors and windows may have been compromised. The								
Building 5 256119 E Closet - St	plumbing, insulation, walls, ceilings, floors and windows may have been compromised. The building's HVAC unit was compromised by salt		Port St Joe, Florida	80021	Buildings 2, 3, 4, 5, 6 & 7	Yes	0%	\$25,000.00	Contract

			The fire suppression system was damaged during								
			the storm with the control system being submerged								
		Buildings 1, 2, and 3 -	by the 7-16 ft. of storm surge. Various sprinkler								
		Sanctuary and	heads, electronics, and routing systems also								
		Offices, Children's	damaged from from top down water after roof and								
		Learning Center, and	window failure as a result of 155 mph winds. In								
		Great Hall Fire	short, the entire system needs to be inspected by								
256110	E	Suppresion System	installer and repaired and/or replaced as is needed.	Removed	Port St Joe, Florida		Yes	0%	\$150,000.00	Contract	
					1001 Constitution						
		Z - Delete Please -	2018 Ford mini bus (shuttle bus) damaged (totaled)		Drive, Port St Joe,						
248746	Е	Vehicle 2	due to hurricane	Removed	Florida, 32456		Yes	0%	\$10.00	Contract	
					1001 Constitution		 				
		Z - Delete Please -	U haul style UMCOR trailers (w/contents) distroyed		Drive, Port St Joe,						
248747	Е	Vehicle 3	due to hurricane	Removed	Florida, 32456		Yes	0%	\$10.00	Contract	
240747				nemoveu	1001 Constitution		 	0/0	\$10.00	contract	
		Z - Delete Please -	U haul style UMCOR trailers (w/contents) distroyed		Drive, Port St Joe,						
248748	Е	Vehicle 4	due to hurricane	Removed	Florida, 32456		Yes	0%	\$10.00	Contract	
240740	L	Venicle 4		Kenioveu			 165	0%	\$10.00	Contract	
		7 Delete Bleess	null behind smaller trailer distroyed due to		1001 Constitution						
240710	-	Z - Delete Please -	pull behind smoker trailer distroyed due to	Dens. 1	Drive, Port St Joe,		N.a.	051	A.A.A		
248749	E	Vehicle 5	hurricane	Removed	Florida, 32456		 Yes	0%	\$10.00	Contract	
					1001 Constitution						
		Z - Delete Please -	pull behind smoker trailers distroyed due to		Drive, Port St Joe,						
248750	E	Vehicle 6	hurricane	Removed	Florida, 32456		Yes	0%	\$10.00	Contract	
		, ,	Bldg. #1 - Sanctuary & Offices - Reconfigured 2nd								
		& Offices -	floor to accommodate 1st floor losses. For								
		Remodeling Second	administrative and office access for employees,							Force Account and	
255083	E	Floor	members, and guests, and community.	Removed	Port St Joe, Florida		Yes	65%	\$20,000.00	Contract	
			Insulation throughout all remaining standing								
			structures was damaged during the storm from								
			being submerged by the 7-16 ft. of storm surge and								
			resulting wave action, and from from top down								
		Buildings 1, 2, and 3 -	water penetration after roof and window failure as a								
		Sanctuary and	result of 155 mph winds. In short, all insulation in all								
		Offices, Children's	walls and ceilings remaining in campus buildings								
			needs to be inspected by installer and repaired								
256111	Е		and/or replaced as is needed.	Removed	Port St Joe, Florida		Yes	0%	\$50,000.00	Contract	
250111	E		Workshop: 3 windows (aluminum frame) 1 –	Keliloveu	1001 Constitution		 	078	\$50,000.00	contract	
		Z - Please Delete -									
249727	-		exterior metal door – garage door (1 car) replaced	Domourd.	Drive, Port St Joe,		Vac	0.09/	610.00	Contract	
248737	E	Redundant	in kind	Removed	Florida, 32456		 Yes	90%	\$10.00	Contract	
		7 Disease Dalata			1001 Constitution						
	-	Z - Please Delete -			Drive, Port St Joe,			001	A		
248742	E	Redundent	Please Delete - Redundant	Removed	Florida, 32456		 Yes	0%	\$10.00	Contract	
			eBldg. #6 – Church Storage Pole Barn - Contents -								
			All contents under the pole barn were listed under								
255135	E	Contents	equipment - none to add.	Removed	Port St Joe, Florida		 Yes	0%	\$0.00	Force Account	
			******* Duplicate Building #1, 2, & 3 - Roof Replace								
			/ Repair - The roof on the Sanctuary & Offices - Bldg.								
			1 - needed immediate replacement per breach and								
			to avoid continual damage and intrusion.								
			Completed. The roof on the Children's Learning								
			Center - Bldg. 2 and the Great Hall - Bldg. 3 - needed								
		Building #1, 2, & 3 -	immediate repair per breach and to avoid continual								
253155	Е	Roof Replace / Repair	damage. Complete.	Removed	Port St Joe, Florida		No	100%	\$100,000.00	Contract	
		1	eBuilding #3 - Great Hall - Structure - Railing. The								
			railing rebuild has been completed on the Rotunda								
		Building 3 - Great Hall	and all pavers for rotunda cleared and relaid. Falling								
253160	Е	- Structure - Railing	hazard & safety issue.	Removed	Port St Joe, Florida		No	100%	\$5,014.00	Contract	
200200	-	, scruccure numing		nemoreu	1. 5. 6 6 6 6 6 7 1 10 10 4			20070	\$3,01 4 .00	contract	

		1										
			eBuilding #3 - Great Hall - Structure - Elevator - The									
			elevator reconstruction / repair has been									
			completed for handicap access to fellowship hall for									
			services and events and upper story of the sanctuary									
		Building 3 - Great Hall	for administrative and office access for employees,									
253165	E	- Structure - Elevator	members, and guests, and community.	Removed	Port St Joe, Florida			No	100%	\$22,926.00	Contract	
			Bldg. #2 - Children's Learning Center built in									
			1962 (Aprx. Size ~ 16,500 ft sq). Damage occurred									
			to all classrooms, kitchen, all bathrooms, closets,									
			hallways, a mechanical closet, and an outdoor									
			walkway and portico (the covered car port at the									
			drop off point located on the north side of the									
			building). Damage caused by Hurricane Michael.									
			Damage occurred to all internal(11) and external(10)									
			doors, internal and external walls, all windows, all									
			floors(luxury vinyl tile), all plumbing and sinks, water									
			pump, all ceilings, kitchen cabinets, HVAC system									
			(equipment?), stand alone HVAC splits, roof, closets,									
			hallways . SHIPPO letter under review. Specific roof									
			damages occurred on the low slope - single ply									
		Building 2 - Children's			1001 Constitution							
		Learning Center -	system was damaged along with all insulation being		Drive, Port St Joe,		Buildings 2, 3, 4, 5,					
248734	E	Structure	moisture damaged.	Active	Florida, 32456	80021	6 & 7	Yes	0%	\$350,000.00	Contract	
210751		Structure	Bldg. #2 -Due to Hurricane Michael: Contents within	<i>i</i> lette	1101100) 52 150	00021			0/0	\$550,000.00	contract	
			the building damaged from A) the walls, doors, and									
		Building 2 - Children's	windows failure B) due to roof and window breach		1001 Constitution							
		Learning Center -	from wind resulting in additional top down water		Drive, Port St Joe,		Buildings 2, 3, 4, 5,					
248739	E	Contents	damage, C) door failures, - See Attached List	Active	Florida, 32456	80021	6 & 7	Yes	0%	\$75,000.00	Contract	
			Bldg. #4 - Workshop contents include damages to							,		
			LED surface lights (9) 4 ceiling fans destroyed – JVC									
			speakers â€" 8 stage lights destroyed â€" live feed		1001 Constitution							
		Building 4 - Workshop	cameras – microphone jack and band monitors -		Drive, Port St Joe,		Buildings 2, 3, 4, 5,					
248741	E	- Contents	attached in documents folder.	Active	Florida, 32456	80021	6 & 7	Yes	0%	\$35,000.00	Contract	
2.107.12			Bldg. #6 – Church Storage Pole Barn – Structure -		1101100, 52 150					\$35,000.00	Contract	
			(Approx. Size ~ 825 ft. sq.) The structure was totaled									
			and subsequently condemned and has been									
			removed in full due to safety issues. Totaled									
			destruction due to A) flood surge of 16 ft plus									
		Building 6 – Storage	resulting wave action, B) wind failure as a result of				Buildings 2, 3, 4, 5,					
255133	E	Pole Barn - Structure	to 155 mph destructive winds.	Active	Port St Joe, Florida	80021	6 & 7	Yes	0%	\$18,000.00	Contract	
										\$10,000.00	contract	
			Bldg. #2 - All Equipment Damaged / Destroyed from									
		Building 2 - Children's	Wind and Flood. Equipment includes IT and Audio									
		Learning Center -	Visual Tools, Kitchen Appliances See Attached List -				Buildings 2, 3, 4, 5,					
252137	Е	Equipment	Computer Equipment See Attached List	Active	Port St Joe, Florida	80021	6 & 7	Yes	0%	\$75,000.00	Contract	
		1	the first definition of the second se			1				÷: 2,500.00		
		Building 4 - Workshon	eBldg. #4 - Attached equipment list TBD in				Buildings 2, 3, 4, 5,					
252143	Е	- Equipment	documents folder	Active	Port St Joe, Florida	80021	6 & 7	Yes	10%	\$10,000.00	Contract	
		1	eBldg. #4 - Workshop - (Aprx. size ~ 500 ft sq) -		1					+==,500,000	22	
			Structural damage to the workshop occurred from									
			wind, rain, flood. Structural analysis needs to be									
			undertaken by engineer - specific damage to all									
		Building 4 - Workshon	internal and external walls, electrical, ceiling, and				Buildings 2, 3, 4, 5,					
252144	Е	- Structure	doors.	Active	Port St Joe, Florida	80021	6 & 7	Yes	10%	\$35,000.00	Contract	
-		1								,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

		1	E Utilities Electrical UNAC Mater		1		1 1			·		
			F - Utilities - Electrical - HVAC - Water									
			Distribution/Disposal - Communications: All of the							1		
			above need repair and / or replacement due to									
			damages suffered from the event. In addition, utility									
			systems should be mitigated / relocated as is									
			possible so that systems are not vulnerable to a									
			subsequent event. Several specific damages include:							1		
			Split head damage to AC units on roof. Electrical									
			damage to all panels and distribution throughout									
			buildings due to hurricane force winds and water.		1001 Constitution							
			Two septic grinder pumps damaged. Server network		Drive, Port St Joe,		Utilities and Storm					
248751	F		and telephone systems damaged.	Active	Florida, 32456	80081	Water Drainage	Yes	5%	\$125,000.00	Contract	
			G - Playground - Preschool - Playground completely									
			destroyed due to Hurricane Michael. includes –							1		
			slide swing set – playhouse- spring loaded bouncy									
			toys- 5' rubberized chain link 15' x 40'									
			fence – playground mulch – picnic table with				1st United					
			umbrella wooden- 2 wood benches – child's		1001 Constitution		Methodist Church 4			1		
			plastic picnic table – 2 canvas shade protection		Drive, Port St Joe,		Parks and					
248752	G	Preschool	sails , 9X9X9.	Active	Florida, 32456	79437	equipment	Yes	0%	\$35,000.00	Contract	
			G - Playground - Elementary - GEO climbing dome									
			– gaga pit – mulch and concrete 35 x 40 –									
			plexiglass outdoor art station – 2 wooden picnic									
			tables w/ umbrellas – perimeter raised garden for				1st United			1		
			education – 5' rubberized playground chain		1001 Constitution		Methodist Church 4					
		G - Playground -	link fence 35' x 40' completely destroyed and		Drive, Port St Joe,		Parks and					
248753	G	Elementary	/ or gone.	Active	Florida, 32456	79437	equipment	Yes	0%	\$35,000.00	Contract	
			G - Playground - Bayside - All Age - the 125' x									
			40' x 5' rubberized chain link fence destroyed									
			– raised bed garden for education (gone) –							1		
			canvas covered pavilion 20' x 20' (damaged)				1st United			1		
			playground mulch 120' x 40' - degradation		1001 Constitution		Methodist Church 4					
		G - Playground -	continues to large play structure due to salt water		Drive, Port St Joe,		Parks and					
248754	G	Bayside - All Age	immersion	Active	Florida, 32456	79437	equipment	Yes	0%	\$75,000.00	Contract	
			G - Historic Triangle Park - 2 benches (wooden park									
			benches) gone Historic bell tower marker destroyed									
			(1950 church bell tower built around it w/ railway							1		
			irons and tiles). Lost many trees - fill dirt -vegetative									
			/ natural solution to de-watering has been removed				1st United					
			due to tree loss which may require a larger storm		1001 Constitution		Methodist Church 4					
			water retention pond (see CAT C item) after storm		Drive, Port St Joe,		Parks and					
248755	G	Park	water engineering analysis and design.	Active	Florida, 32456	79437	equipment	Yes	0%	\$185,000.00	Contract	
240733	0	I UIK	nater engineering analysis and design	Active	1101100, 52450	75457	equipment	105	0/0	\$105,000.00	Contract	