

FEMA-DR-4399-FL

SITE INSPECTION MITIGATION REPORT FIRST UNITED METHODIST CHURCH OF PORT ST. JOE

Type: WO# 38351
Applicant: First United Methodist Church of Port St. Joe FIPS#: 045-12767-00
County: Gulf
Site: Playground – Bayside (All Age)
Date: 05/28/2019
Location: 1001 Constitution Drive, Port St. Joe, FL 32456
Lat/Long: Refer to Site Inspection Report
Attendees: Refer to PA Grants Manager for list of attendees

DI# 248754 Category: G 0 % work complete

Known dimensions, damages, and current conditions:

This DI consists of damages to the playground, exclusive of most playground equipment, located at the southwest corner of the First United Methodist Church (FUMC) structure and variously referred to as the Bayside – All Age Playground or the Bayview Adventure Playground. In addition to the coated chain link fence and gate that formerly encompassed the playground on two sides and the playground mulch that was washed away, other damaged or lost/destroyed features associated with this DI include a raised bed garden for education, a canvas covered pavilion, wooden picnic tables with umbrellas, a hexagonal ball pit (fence and gate), and picnic tables.

Cause of Damage:

High winds from Hurricane Michael, and the associated storm surge from St. Joseph Bay that rolled over the FUMC campus, was the cause of all the lost and damaged items associated with this DI. In some instances, falling trees may have exacerbated damage impacts to certain components. The storm surge variously damaged, washed away, or corroded specific items.

Repair to pre-disaster condition:

The Applicant's intent with respect to the losses and damages incurred under this DI is to replace the items to pre-disaster conditions with in-kind equipment and materials.

Potential mitigation measures:

Based on the cause of the damage, discussion with the Applicant, and the nature of the items damaged, no practical, potential mitigation measures have been identified specific only to this DI, nor are any sought by the Applicant. However, the Applicant's comprehensive mitigation approach for the FUMC campus would potentially mitigate some of the types of damages that occurred under this DI. Specifically, as part of the Applicant's overall mitigation strategy for the campus, FUMC envisions constructing a fortified wall with strategically located floodgates around the campus building complex that would also encompass the Bayside Playground. In addition, a seal would be placed on the manhole in the playground to prevent backflow, and the playground drainage system would be enhanced.

Photos: See attached photo sheets.

FEMA HM Attendee: Anthony J. Tawa, Jr. (CCPRS)
Title: 406 Mitigation Specialist
Phone number: 850-567-5211

FEMA-DR-4399-FL

FEDERAL EMERGENCY MANAGEMENT AGENCY

Photo Sheet

| | | | | |
|--|---------------------------|---------------------|------------------|-------------|
| DECLARATION NO. FEMA DR 4399 | DI#: 248754 WO#: 38351 | FIPS#: 045-12767-00 | DATE: 05/28/2019 | CATEGORY: G |
| APPLICANT: First United Methodist Church of Port St. Joe | | COUNTY: Gulf | | |




Photo 1: Location of Bayside (Bayview) Playground relative to FUMC facility. Refer to SIR for Lat/Long (typ).

Photo 2: Portion of Bayside Playground prior to Hurricane Michael.



Photo 3: Bayside Playground (northern end).

Photo 4: Bayside Playground (southern end).

FEMA-DR-4399-FL

FEDERAL EMERGENCY MANAGEMENT AGENCY

Photo Sheet

| | | | | | |
|-----------------|----|-------------|--------------|------------------|-------------|
| DECLARATION NO. | | DI#: 248754 | FIPS#: | DATE: 05/28/2019 | CATEGORY: G |
| FEMA | DR | 4399 | 045-12767-00 | | |

| | |
|--|--------------|
| APPLICANT: First United Methodist Church of Port St. Joe | COUNTY: Gulf |
|--|--------------|



Photo 5: Damaged fence (mid-section of Bayside Playground).



Photo 6: Damaged fence (southern section of Bayside Playground).



Photo 7: Google Maps satellite view of selected FUMC campus features (see red ovals and arrows).

Photo 8: Not used.